

F-02



NO.	FUSE NAME	FUSE	NO.	FUSE NAME	FUSE
①	<PW>	<30A>	⑪	F.WIP	25A
②	<M.DEF>	<7.5A>	⑫	R.WIP	15A
③	*	*	⑬	ENG	5A
④	<ENG 3>	<20A>	⑭	METER	10A
⑤	*	*	⑮	SAS	10A
⑥	P.OUTLET	15A	⑯	<S.WARM>	<15A>
⑦	<SHIFT/L>	<5A>	⑰	ABS/DSC	5A
⑧	CIGAR	15A	⑱	<EHPAS>	<5A>
⑨	MIRROR	7.5A	⑲	<ENG2>	<15A>
⑩	A/C	10A			